



165-066-901
Issue A 07/07/1998
Sheet 1 of 6

Order Number

Serial Number

PRODUCT/TEST MANUAL

2V66K1

OLTC Voltage Runaway Prevention Relay

Issue Level	Date	Summary of changes
A	07/07/1998	Initial issue.

Due to RMS continuous product improvement policy this information is subject to change without notice.

Document updated	Checked	Registered	.pdf file created	.pdf uploaded to web site

1. DESCRIPTION OF OPERATION

The 2V66 is a definite time under and over voltage relay. The output contacts will change state if the sensing voltage remains outside the set limits for the time of the setting on the timer. If the sensing voltage falls below 80% the under voltage feature will cause the relay to inhibit any output contact operation. LED indicators on the front panel of the relay indicate the operational status of the under/over voltage and timing functions. A switchmode power supply generates the voltages needed for operation of the internal electronics, this makes a wide range of operating input voltages possible.

2. SPECIFICATIONS

Auxiliary Supply	40 - 275 volts AC or DC
Auxiliary Burden	Approx 10 watts operated.
Sensing Voltage	63.5 / 110 volts AC
Hysteresis	< 0.5%
Sensing setting range	
O/V	105 - 120 volts AC
U/V	95 - 110 volts AC
Undervoltage lockout	< 80% of nominal
Time setting range	
O/V	1 - 300 seconds
U/V	1 - 300 seconds
Output contacts	1 changeover per function

3. TEST EQUIPMENT REQUIRED

Adjustable AC Supply	C R O
Digital Multimeter	Timer

4. ASSOCIATED DRAWINGS

165-066-101	Wiring Diagram
660-289-201	Schematic Diagram Primary PCB
660-289-301	Loading Diagram Primary PCB
660-290-201	Schematic Diagram Secondary PCB
660-290-301	Loading Diagram Secondary PCB

5. HIGH VOLTAGE TESTING

- a) Apply 2KV 50Hz test for 1 minute between terminal Groups A and B.
- b) Apply three 5KV 1/50 impulses of each polarity between terminal Groups A and B.

<u>Group A</u>	<u>Group B</u>
A1 TO A12	C1 TO C12
A1,A2,A7,A,8,A9,C10,C11,C12,C4,C5,C6	A4,A5,A6,A10,A11,A12,C1,C2,C3,C7,C8,C9
A1,A2,A4,A5,A6,C10,C11,C12,C7,C8,C9	A7,A8,A9,A10,A11,A12,C4,C5,C6,C1,C2,C3
All terminals	Frame

6. CALIBRATION & TEST PROCEDURE

Preliminary checks & transformer calibration

- a) Apply auxiliary supply to terminals 1 & 2, check the correct voltages appear on the test points as per the following table. Measure with respect to TP01-A

TP01-B	TP01-F	TP01-D	TP01-H
+24 VDC	+18 VDC	+12 VDC	-12 VDC

Transformer calibration

- a) Apply the 110 volts AC sensing voltage to terminals 4 & 6, use a voltmeter to monitor this voltage.
- b) Monitor between TP01-A (negative) and TP01-G, Adjust VR01 for a reading of 11.000 volts AC.
- c) Monitor between TP01-A (negative) and TP01-L and adjust VR03 for 10.000 volts DC.

Overvoltage calibration

- a) Monitor between TP01-K and TP01-A (negative) with an oscilloscope, adjust "O/V set (VR04)" and AC input volts to 120 and adjust VR02 until TP01-K just goes high.
- b) Set "O/V set" to 105 volts and adjust VR05 until TP01-K goes high.
- c) Repeat steps a) and b) until scale is calibrated.
- d) Ensure the hysteresis measured at TP01-K and TP01-A (negative) is not less than 99.5 % at maximum setting.
- e) Record results below.

Nominal	Minimum Pick up	Maximum Pick up	Actual	Drop out	Hysteresis
105	104.4	105.6			
110	109.4	110.6			
115	114.4	115.6			
120	119.4	120.6			

Undervoltage calibration

- a) Set VR08 to approximate mid scale and "U/V set (VR07)" to 110 volts, apply 110 volts AC to the sense input.
- b) Monitor between TP01-J and TP01-A (negative) with an oscilloscope and adjust VR06 until TP01-J just goes high.
- c) Set "U/V set" (VR07) to 95 volts and adjust VR08 until TP01-J just goes high.
- d) Repeat steps b) and c) until scale is calibrated.
- e) Ensure the hysteresis measured at TP01-J and TP01-A (negative) is not less than 99.5 % at maximum setting.

Undervoltage calibration (Cont)

f) Record results below.

Nominal	Minimum Pick up	Maximum Pick up	Actual	Drop out	Hysteresis
95	94.45	95.55			
100	99.45	100.55			
105	104.45	105.55			
110	109.45	110.55			

Undervoltage lockout calibration

a) Set input sensing volts to 88, monitor TP01-I and TP01-A (negative), adjust VR09 until this pin just goes low Remove test leads.

Nominal	Minimum	Maximum	Actual
88	87.6	88.4	

Overvoltage timer calibration

- Set sensing input voltage to 120 and "O/V set (VR04)" control to 110
- Monitor TP02-A and TP01-A (negative) with a frequency counter set to monitor period. Adjust VR10 to obtain a span of 300:1 irrespective of actual period.
- Set timer control "O/V Delay" (VR11) to maximum setting and select C59,60,61 to give a period reading of 9.15 mS.
- Record results at nominal time settings below.

Nominal (seconds)	Minimum	Maximum	Actual
1	0	15	
50	35	65	
100	85	115	
150	135	165	
200	185	215	
250	235	265	
300	285	315	

6. CALIBRATION & TEST PROCEDURE (Cont)

Undervoltage timer calibration

- a) Set sensing input voltage to 100 and "U/V set (VR07)" control to 110
- b) Monitor TP02-I and TP01-A (negative) with a frequency counter set to monitor period. Adjust VR12 to obtain a span of 300:1 irrespective of actual period.
- c) Set timer control "U/V Delay" (VR13) to maximum setting and select C65,66,67 to give a period reading of 9.15 mS.
- d) Record results below

Nominal (seconds)	Minimum	Maximum	Actual
1	0	15	
50	35	65	
100	85	115	
150	135	165	
200	185	215	
250	235	265	
300	285	315	

7. GENERAL & FUNCTIONAL

- a) Check operation of LED's.

OK

- b) Check operation of Power supply fail contacts and Undervoltage Lockout contacts.

- c) Check that the relay is electrically sound and mechanically robust as per Standard Inspection & Test Schedule 903-000-026.

PASS

TESTED BY: _____

DATE: _____

8. CONNECTION DIAGRAM

